




J. MERRIAM  
SERIAL NO. 09/695,536  
PETER H. PRIEST (919-806-1600)

Replacement Sheet

1/12

FIG. 1



J. MERRIAM 2  
SERIAL NO.: 09/695 536  
PETER H. PRIEST (919-806-1600)

Replacement Sheet

2/12

FIG. 2A




FIG. 2B




FIG. 2C





FIG. 2D



FIG. 2E



J. MERRIAM 2  
SERIAL NO.: 09/695 ~~536~~  
PETER H. PRIEST (919-806-1600) Replacement Sheet

3/12

FIG. 3

310






FIG. 4




5/12

FIG. 5




6/12

FIG. 6



7/12

FIG. 7



J. MERRIAM 2  
SERIAL NO.: 09/695 536  
PETER H. PRIEST (919-806-1600)

8/12

FIG. 8




FIG. 9A



FIG. 9B




FIG. 9C






FIG. 9D




9/12

FIG. 10




10/12

FIG. 11



11/12

FIG. 12



12/12

